




1. Algae starting to grow




2. Algae spreading to the floor



3. Tiles begin to fall off



4. Pool has been repaired without draining. Clients are still able to use the pool throughout the repair process.



5. Before and after comparison